
Distortion after side branc



Stent Distortion Repaired by Main Branch Redilatation with some loss of Side-**Branch Size**

3mm side-branch dilatation

3.5mm main branch dilatatior Ormiston et al Cathet Cardiovasc Interv 1999;47:258-264.



Side-branch distortion is repaired by main vesse post-dilatation or better by "kissing" balloons

3mm side-branch dilatation

3.5mm main branch dilatation

Kissing balloons

Ormiston et al Cathet Cardiovasc Interv 1999;47:258-264.

